

Task Status Results (Printed on: 6/21/2022 12:48 PM)
Company Task List: Summit Natural Gas B31Q Task List
Company: Anderson Welding



Grimaldi, Ryan
EWN-899967
Supervisor(s):

Task Code	Task Name	Current Completion Date	Valid Until	Status
0141	Perform Visual Inspection for Atmospheric Corrosion (1:1)	6/21/2022	6/21/2025	✓
0161	Perform Visual Inspection for Internal Corrosion (1:1)	6/21/2022	6/21/2025	✓
0561	Pressure Test - Nonliquid Medium - MAOP Less Than 100 Psi (1:2)	6/21/2022	6/21/2025	✓
0641	Visually Inspect Pipe and Components Prior To Installation (1:2)	6/21/2022	6/21/2025	✓
0731	Joining of Pipe -- Flange Assembly (1:4)	6/21/2022	6/21/2025	✓
0801	Welding (1:0)			!
0811	Visual Inspection of Welding and Welds (1:1)			!
0861	Installation of Steel Pipe in a Ditch (1:5)	6/21/2022	6/21/2025	✓
0991	Coating Application and Repair -Brushed or Rolled (1:5)			!
1020	Perform Electrical Inspection of Pipe Coating (Holiday Detection of Jeeping) (1:1)			!
1321	Damage Prevention During Excavation Activities by or on Behalf of The Operator (1:1)	6/21/2022	6/21/2025	✓