

## Task Status Results (Printed on: 9/6/2023 1:23 PM) Company Task List: Summit Natural Gas B31Q Task List Company: Anderson Welding



Rowe, Chris EWN-362020 Supervisor(s):

Task Code Task Name							Current Completion Date				te Valid Until	Status	
0141	Perform Visual Inspection for Atmospheric Corrosion (1:1)							9/6/2023				9/6/2026	$\bigcirc$
Туре		ID	E	Evaluation Title				Complete	ed V	alid Until	Training	Training Required	Status
Computer Bas Training	sed	188	38	EWN-CBT-Perform Vis 0141)	sual Inspection for Atmos	spheric Corrosion		9/6/2023	3 9	9/6/2026	9/6/2023	~	$\oslash$
Performance	Evaluatior	807	34 E	EWN-PE-Perform Visu	al Inspection for Atmos	oheric Corrosion (014	11)	9/6/2023	}	Non- Expiring			$\odot$
0151	Perform	n Visua	l Insp	pection of Buried Pi	pe and Components W	hen Exposed (1:1)				9/6/20	23	9/6/2026	
Туре		ID	Eva	aluation Title				Compl	eted	Valid Unti	I Training	Training g Required	Status
Performance Evaluation		80735		N-PE-Perform Visual oosed (0151)	Inspection of Buried Pip	e and Components V	When	9/6/20	)23	Non- Expiring			$\odot$
Computer Bas Training	sed	85348		N-CBT-Perform Visua en Exposed (0151)	al Inspection of Buried Pi	ipe and Components		9/6/20	)23	9/6/2026	9/6/202	3 🗸	$\oslash$
0201	Perform	n Visua	l Insp	pection of Installed I	Pipe and Components	for Mechanical Dam	nage	(1:1)		9/6/20	23	9/6/2026	
Туре		ID	Eval	luation Title				Com	pleted	Valid Until	Trainin	Training g Required	Status
Computer Bas Training	sed	85118		I-CBT-Perform Visual hanical Damage (020	Inspection of Installed F 1)	Pipe and Components	s for	9/6/2	2023	9/6/2020	6 9/6/202	23 🗸	$\oslash$
Performance Evaluation		85119		N-PE-Perform Visual I hanical Damage (020	nspection of Installed Pi 1)	pe and Components	for	9/6/2	2023	9/6/2020	6		$\oslash$
0991 Coating Application and Repair -Brushed or Rolled (1:3)								9/6/2023			23	9/6/2026	$\bigcirc$
Туре		ID	E	Evaluation Title			(	Complete	d Va	alid Until	Training	Training Required	Status
Computer Bas	sed Trainir	ng 137	82 E	EWN-CBT-Coating Ap	plication and Repair: Br	ushed or Rolled (099	1)	9/6/2023	g	/6/2026	9/6/2023	$\checkmark$	$\odot$
Performance	Evaluation	808	57 E	EWN-PE-Coating App	lication and Repair• Bru	shed or Rolled (0991)	)	9/6/2023	No	n-Expiring			$\odot$
1001 Coating Application and Repair -Sprayed (1:3)							9/6/2023			9/6/2026	Ø		
Туре		IC	)	Evaluation Title			Con	npleted	Valid	l Until T	raining	Training Required	Status
Performance	Evaluatior	80	858	EWN-PE-Coating A	oplication and Repair « S	Sprayed (1001)	9/6	6/2023	Non-E	Expiring			$\oslash$
Computer Bas	sed Trainir	ng 85	5121	EWN-CBT-Coating	Application and Repair: \$	Sprayed (1001)	9/6	6/2023	9/6/	2026 9	)/6/2023	$\checkmark$	$\oslash$
1011 External Coating Application and Repair- Wrapped (1:3)								9/6/2023			9/6/2026	Ø	
Туре		ID		Evaluation Title				Complete	ed Va	alid Until	Training	Training Required	Status
Computer Bas	sed Trainir	ng 157	'80 E	EWN-CBT-External C	oating Application and R	epair: Wrapped (101	1)	9/6/2023	3 9	9/6/2026	9/6/2023	~	$\oslash$
Performance	Evaluation	808	59 E	EWN-PE-External Co	ating Application and Re	pair- Wrapped (1011)	)	9/6/2023	3 9	9/6/2026			$\odot$